



Product Release Information: LE Firmware 01.17.01

Product	LE
Version Number	01.17.01
Firmware Release Date	March 2026
Customer Support	For more information or support, visit the ENGAGE website.

Attention:

This document contains the **Release Notes** for LE device firmware version **01.17.01**. This version includes feature updates and improvements made after the LE product firmware 01.16.02 released in October of 2025.

Installation and Update Notes:

Device firmware updates are available through the ENGAGE™ cloud database.

From the ENGAGE web portal, each lock may be independently selected by the site administrator to have the latest firmware downloaded during the next scheduled Wi-Fi connection. The site administrator may connect locally to individual locks with the ENGAGE mobile application to update an LE with the latest firmware.

Firmware versions that will be installed with this update:

- **Main Application** **01.17.01**
- **Reader Application** **02.30.00**
- **BLE Application** **02.13.13.547,01.10.05,03-1.7.0**
- Wi-Fi Application: 02.15.0.1

NOTE: The **BOLD** item(s) are updated from the previous release

Other system components versions to be used with this release: (or newer)

- **Gateway** **01.69.04**
- MT20W 41.00.00
- **Android Application** **4.8.28**
- **iOS application** **3.19.3**
- **ENGAGE** **8.8.0**

LE RELEASE NOTES: LE Firmware 01.17.01

SES-20260311A



ALLEGION™

Who should update?

Allegion suggests that customers utilize the latest firmware release to take advantage of the latest functionality, bug fixes, and security enhancements. We strive to provide the best products and services for our customers.

Specifically, any customer interested in any of the following Recent Changes should update their devices.

Recent Changes:

- Updated to latest BLE Platform version
- Improved the ability to handle large HTTP response during Wi-Fi Check-in
- Improved lock response when Wi-Fi module fails to initialize
- Fixed an issue where MIFARE Classic was not read due to UID
- Fixed an issue where Apple No-Tour credentials were not working properly
- Added requirement for Site Wide No-Tour to be Selected for NFC No-Tour credentials to be supported
- General Security Improvements – New Firmware Baseline
 - Version 02.17.01 is the new firmware baseline. Firmware cannot be downgraded below this version.

Revision	COMMENTS	DATE
SES20260311A	Release Notes for LE as part of ENGAGE 8.8.0	03-18-26